



540 S. St. Clair St. Toledo OH 43604  
419-720-8800  
Greatlakesparty.com

---

## **Popcorn Machine Instructions**

### **Step 1**

Place unit on a secure table top and plug unit into electricity outlet. 120 Volt, 15 Amp circuit. Be sure electrical source is sufficient to properly power machines

### **Step 2**

Turn Kettle heat and kettle motor switch "ON" Allow 7-10 Minutes for kettle to warm.

### **Step 3**

Pour 6-8 ounces of prepared kernels into kettle

### **Step 4**

When corn has finished popping dump kettle

### **Step 5**

Repeat steps 3 & 4 until you have made the desired amount of popcorn.

### **Step 6**

Once you have made enough popcorn turn motor switch and heat off. Turn on lights and warmers to keep popcorn warm

---

## **Cleaning**

After you're finished using the machine. Take out all debris in all parts of the machine including tray kettle and holding compartment

---

## **Parts**

Be sure to return all the supplied parts:

Popcorn Machine

Scoop

Tray

---

## **Tips**

Caution: Kettle could be hot and cause serious burns if touched.

Leaving popcorn in kettle for too long can cause it to burn.

If a batch of popcorn has been burnt. You must first clean the inside of the kettle before preparing another batch.